

Date: Monday, 03/12/2007 3:30:43 PM  
 User: Jason Murdoch

## Process Sheet

<b>Customer</b>	: CU-DAR001 Dart Helicopters Services		<b>Drawing Name</b>	: WEARPLATE KIT,STANDARD		
<b>Job Number</b>	: 36091		<b>Part Number</b>	: D412726141		
<b>Estimate Number</b>	: 12199		<b>Drawing Number</b>	: N/A		
<b>P.O. Number</b>	:		<b>Project Number</b>	: N/A		
<b>This Issue</b>	: 03/12/2007	<b>S.O. No.</b> :	<b>Drawing Revision</b>	: N/A		
<b>Prsht Rev.</b>	: NC		<b>Material</b>	: N/A		
<b>First Issue</b>	: 03/12/2007	<b>Type</b> :	SMALL /MED FAB			
<b>Previous Run</b>	:		<b>Due Date</b>	: 04/12/2007		Qty: 1 Um: Each
<b>Written By</b>	:		<i>[Signature]</i> 07-12-07			
<b>Checked &amp; Approved By</b>	:					
<b>Comment</b>	:		Est Rev:A 05.05.12 New issue KJ/JLM			

## Additional Product

Job Number:



Seq. #:	Machine Or Operation:	Description :
1.0	DC	DOCUMENT CONTROL 
		<b>Comment:</b> DOCUMENT CONTROL Photocopy bluefile and create labels per PPP D412-726-142 CHG001 <i>d 07/26/07</i>
2.0	PACKAGING 1	PACKAGING RESOURCE #1 
		<b>Comment:</b> PACKAGING RESOURCE #1 Pick Packing Kit
3.0	D33151	Wearplate, LH Fwd 
		<b>Comment:</b> Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s) Pick: Packing Kit Qty Part Number Description Batch 1 D3315-1 Wearplate, LH Fwd <i>25728</i> <i>LC</i>
4.0	D33153	Wearplate, LH Center 
		<b>Comment:</b> Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s) Pick: Packing Kit Qty Part Number Description Batch 1 D3315-3 Wearplate LH Center <i>25726</i> <i>LC</i>
5.0	D33155	Wearplate, LH Aft 
		<b>Comment:</b> Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s) Pick: Packing Kit Qty Part Number Description Batch 1 D3315-5 Wearplate LH Aft <i>325727</i> <i>LC</i>

Date: Monday, 03/12/2007 3:30:44 PM  
User: Jason Murdoch

## Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: WEARPLATE KIT, STANDARD

Job Number: 36091

Part Number: D412726141

Job Number:



Seq. #:	Machine Or Operation:	Description :
---------	-----------------------	---------------

6.0	AN35A	Bolt
-----	-------	------



Comment: Qty.: 40.0000 Each(s)/Unit Total : 40.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

40 AN3-5A Bolt M100188

7.0	AN960JD10L	Washer
-----	------------	--------



Comment: Qty.: 40.0000 Each(s)/Unit Total : 40.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

40 AN960JD10L Washer M107374

8.0	QC4	INSPECT 100% KITS FOR COMPLETENESS
-----	-----	------------------------------------



Comment: INSPECT 100% KITS FOR COMPLETENESS

9.0	PACKAGING 1	PACKAGING RESOURCE #1
-----	-------------	-----------------------



Comment: PACKAGING RESOURCE #1

Identify and pack for shipping as per PPP D412-726-141

Location:

PPP Rev:

Draft

7/12/04 SD(1)

10.0	QC21	FINAL INSPECTION/W/O RELEASE
------	------	------------------------------



Comment: FINAL INSPECTION/W/O RELEASE

7/12/04

Job Completion



7/12/04

Date: Tuesday, 12/4/2007 7:44:26 AM --  
 User: Kim Johnston

## Process Sheet

Customer	CU-DAR001 Dart Helicopters Services			Drawing Name	WEARPLATE KIT,STANDARD		
Job Number	36091			Part Number	D412726141		
Estimate Number	12199			Drawing Number	N/A		
P.O. Number				Project Number	N/A		
This Issue	12/4/2007	S.O. No.		Drawing Revision	N/A		
Prsht Rev.	NC			Material	N/A		
First Issue	12/3/2007	Type	SMALL /MED FAB	Due Date	12/4/2007	Qty:	1 Um: Each
Previous Run							
Written By							
Checked & Approved By							
Comment	Est Rev:A 05.05.12 New issue KJ/JLM						

## Additional Product

Job Number:



Seq. #:	Machine Or Operation:	Description :
1.0	DC	DOCUMENT CONTROL 
<b>Comment:</b> DOCUMENT CONTROL Photocopy bluefile and create labels per PPP D412-726-142 CHG001		
2.0	PACKAGING 1	PACKAGING RESOURCE #1 
<b>Comment:</b> PACKAGING RESOURCE #1 Pick Packing Kit		
3.0	D33151	Wearplate, LH Fwd 
<b>Comment:</b> Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s) Pick: Packing Kit Qty Part Number Description Batch 1 D3315-1 Wearplate, LH Fwd _____		

Job Completion



REFERENCE ONLY